

What firmware changes have taken place on the Maretron DSM570?

Article Number: 712 | Rating: Unrated | Last Updated: Fri, Mar 18, 2022 9:24 PM

DSM570 Firmware Versions

What firmware changes have taken place on the Maretron DSM570 display?

Update your device using the [N2KAnalyzer](#) software tool.

1.8.6.3 (2022-03-16)

- Fix rolling toad trail issue on VGA resolution display
- Correct Demo icon position on VGA resolution display
- Change screen lock mode selection from buttons combination on power up to power down options selections
- Add testmode command "startup" to support startup options
- Fix rolling road crash when ellipse cannot be drawn
- Correct DCM menu display text GEL

1.8.5.2 (2021-10-07) - Not Released

- In power off state, keep internal power supply active if N2K supply voltage is less than 10V

1.8.4.6 (2021-04-21)

- Support Yaw (PGN# 127257)
- Support Generic Sensor device
- Support Standard N2K Label (PGN# 130060)
- Support Shaft Seal Temperature (15) for DD291 (Bug #4702)
- Fix annunciator stop working after deleting issue (Bug #4652)
- Add units for Force (Bug #3749)

1.8.3.2 (2020-08-14)

- Support TSM810C, TSM1210C, MBB300C configuration
- For FFM100 configuration menu, always display K-Factor as 1000 when the K-Factor on FFM100 is 1000. This fix an issue caused after load default to FFM100 and the DSM display the old K-Factor value before loading default, this issue also fixed in the FFM100 SW 1.4.1.1
- Support CLM100 SW 1.2+
- Support CLM100 configuration for Battery, Engine, Transmission, and Vessel Devices

1.8.1.2 (2018-10-15)

- Initial customer release

Posted - Tue, Jul 14, 2020 8:11 PM. This article has been viewed 1289 times.

Online URL: <https://www.maretron.com/support/knowledgebase/phpkbv7/article.php?id=712>