

# What firmware changes have taken place on the Maretron SSC300?

What firmware changes have taken place on the SSC300?

## 1.0.6.1(2016-8)

- Corrected a problem where "SSC300" was not recognized in configuration commands sent over the NMEA 0183 interface (3707)

## 1.0.5(2016-4)

- Manufacturing improvement

## 1.0.4.1(2015-10)

- Corrected a problem where negative pitch and roll values could be incorrectly transmitted on NMEA0183 (3659)
- Corrected a problem where the NMEA0183 interface could start with the wrong baud rate (3652)

## 1.0.3.1 (2015-11)

- Corrected a problem where factory defaults weren't correctly loaded
- Corrected a problem with status notification during magnetic deviation calibration (3619)

## 1.0 (2015-08)

- Initial Release

Online URL:

<https://www.maretron.com/wp-content/phpkbv96/article.php?id=628>