

What firmware changes have taken place on the Maretron WSO200 Ultrasonic Wind & Weather Station?



WSO200 Firmware History

What firmware changes have taken place on the Maretron WSO200.

1.1.2.1 (2024-06-12)

- Transmit 130310 as default (Bug #WSO200SW-5)
- Transmit 130311 as default (Bug #WSO200SW-5)
- Transmit 130312 as default (Bug #WSO200SW-5)

1.1.1.2 SW (2024-04-03)

- Change CAN bit timing from 7TQ to 14TQ which seems to fix the DST conflict issue (Bug #WSO200SW-4)

1.1.1.1 SW (2023-10-23)

1.1.1 BOOT

- Change NMEA2000 Manufacturer to 137 (Maretron) (Bug

#WSO200SW-1)

1.0.2.1 SW (2023-06-22)

1.0.3 BOOT

- Update to NMEA2000 version 3.000
- Pass N2K Certification v3.2

1.0.1.14 SW (2022-04-28)

1.0.3 BOOT

- Initial release
- Support STM32F3 platform and Unictron A300A sensors

Online URL:

<https://www.maretron.com/wp-content/phpkbv96/article.php?id=729>