How many J2K100s do I need if I have two engines and I would like convert the J1939 information from both engines to NMEA 2000?

You need one J2K100 per engine. If you have two engines with J1939 interfaces, you would need two J2K100s to convert the information from both engines to NMEA 2000.

Online URL:
https://www.maretron.com/wp-content/phpkbv96/article.php?id=266