# What firmware changes have taken place on the Maretron ALM100 Alarm Module?

What firmware changes have taken place on the Maretron ALM100 Alarm Module?

Update your device using the N2KAnalyzer software tool paired with a Maretron gateway.

## ALM100 Firmware Versions

### 1.0.6 (2010-08-13)

- Updated supported NMEA 2000 database version to 1.300

### 1.0.5 (2009-05-20)

- Corrects a stability issue that could arise when multiple alerts are active simultaneously

**1.0.4 (2009-02-23)**

- Improved support for labeling of the device and its channels to store more pertinent information

**1.0.3 (2008-11-26)**

- TX 130824 periodically every 10s all the time  (if it is not disabled)

**1.0.2 (2008-11-05)**

- Corrected the reported LEN (Load Equivalent Number) to 2 (100mA maximum)

**1.0.1 (2008-10-21)**

- Initial public release