What firmware changes have taken place on the Maretron SIM100?

What firmware changes have taken place on the Maretron SIM100?

Update your device using the N2KAnalyzer software tool.

SIM100 Firmware Versions

1.2.2.2 (2015-08-29)

- Ensured that PGN 127501 is transmitted immediately when the switch bank instance is changed so that all displays can immediately see the changed instance number (1334)

1.2.1.1 (2015-10-01)

- Manufacturing Improvements

1.1.2.5 (2013-07-19)

- Added support for hardware timers and counters for each channel. These timers and counters are calculated and stored within the SIM100 and do not depend on N2KView to be running.
- Updated the supported NMEA 2000 database version to 2.000

1.1.1 (2009-02-23)

- Updated labeling support

1.0.2 (2008-10-21)

- Added support for labeling so that the device can easily be identified with a user-programmable string.

1.0.1 (2008-08-25)

- Initial public release