

# What firmware changes have taken place on the Maretron TLM200?

Article Number: 427 | Rating: Unrated | Last Updated: Mon, Aug 29, 2016 5:09 PM

2.0.2.3 (2016-08-29):

- Correct fluid source transmitted in Channel PGN (3959)
- Corrected a problem where the device could lose its instance information after a power cycle (3964, 3965, 3966, 3967)

2.0.1.5 (2015-10)

- Initial Release to support Hardware Version 2

1.1.8.3 (2014-10-30)

- Added support for real-time display of depth readings during calibration

1.1.5 (2009-08-10)

- Added capability to have the level/distance table be configured by N2KAnalyzer

1.1.4 (2009-04-28)

- Initial public release

Posted - Mon, Oct 21, 2013 1:49 PM. This article has been viewed 2965 times.

Online URL: <https://www.maretron.com/support/knowledgebase/phpkbv7/article.php?id=427>