

# What firmware changes have taken place on the Maretron TLM100?

---

## 2.0.2.3 (2016-08-29):

- Correct fluid source transmitted in Channel PGN (3959)
- Corrected a problem where the device could lose its instance information after a power cycle (3964, 3965, 3966, 3967)

## 1.1.8.3(2014-10-30)

- Added support for real-time display of depth readings during calibration

## 1.1.6 (2011-10-01)

- Updated supported NMEA 2000 database version to 1.301

## 1.1.5 (2009-08-10)

- Added capability to have the level/distance table be configured by N2KAnalyzer

## 1.1.4 (2009-03-20)

- Made improvements to label implementation

## 1.1.3 (2009-02-06)

- Corrected issue that caused custom calibration to not work

## 1.1.2 (2009-02-03)

- Made improvements to label implementation

1.1.1 (2009-01-30)

- Made improvements to label implementation

1.1.0 (2009-01-07)

- Initial public release

Online URL:

<https://www.maretron.com/wp-content/phpkbv96/article.php?id=425>