

What firmware changes have taken place on the Maretron SMS100?

2.0.3.1 (2013-07-25)

- Change NMEA2000 Class/Function to 70/171 (Bug #2668)

2.0.2.1 (2013-07-19)

- Corrected a problem where, upon receipt of the STATUS command, the SMS100 would return parameter values from any available instance, if the instances specified in the User's Manual were not available. Now, upon receipt of the status command, the SMS100 returns parameter values from only those instances specified in the User's Manual.

2.0.1.9 (06-05-2013)

- Initial release

Online URL:

<https://www.maretron.com/wp-content/phpkbv96/article.php?id=581>