

TMT7839

Universal J1587/J1708 to J1939 Translator

Wiring Information

©2014 Canadian Automotive Instruments Ltd.



Note: Proper J1939 terminating resistors must be observed independent of the TMT7839 device.

