

Why do I hear a clicking sound when the DST100 is plugged in?

Article Number: 199 | Rating: Unrated | Last Updated: Sun, Jun 22, 2008 8:52 PM

The clicking sound is the DST100 transmitting a sound wave. The sound wave is reflected off the bottom and returns to the DST100. The DST100 calculates the distance to the bottom by measuring the round trip time of the sound wave.

Posted - Sun, Jun 22, 2008 8:52 PM. This article has been viewed 2492 times.

Online URL: <https://www.maretron.com/support/knowledgebase/phpkbv7/article.php?id=199>