

What firmware changes have taken place on the Maretron TMP100?

What firmware changes have taken place on the Maretron TMP100 Temperature Monitor?

Update your device using the [N2KAnalyzer](#) software tool.

TMP100 Software Revision History:

1.1.2.7 (2013-07-02)

- Allow user to disable channel (bug # 1162)
- Change NMEA 2000 Database Version to 2.000 (bug # 2632)
- Support HW 1.x and 2.x (bug # 2633)
 - HW 1.x --> HW 2.x
 - Change EEPROM to 8KB
- Support PGN 130316 (Temperature Extended Range) (bug # 2558)

1.1.1 (2009-02-23)

- Added support for labeling so that the device can easily be identified with a user-programmable string

1.0.3 (2008-11-10)

- Allow channels to be programmed with different source types but the same instance number

1.0.2 (2008-11-07)

- Made PGN's 130310 and 130311 enabled by default
- Changed behavior when multiple channels are configured with the same source and instance so that data will be transmitted only from the lowest numbered hardware channel

1.0.1 (2008-11-05)

- Initial public release

Online URL:

<https://www.maretron.com/wp-content/phpkbv96/article.php?id=428>